












## Modelos integrados en obd by isacar cuadros

61 modelos, 18  
Marcas

	referencia	Funcionamiento	Diagnosis	Cable ref
<b>Audi</b> 				
Audi a3 8P 2003-2010	8P0 920 930Q	100%	100%	C0001
Audi a4 B5 1999-	8D0919881J	100%	0% Externa	C0001
Audi a4 B7 2004-2008	103690183000%	100% / 100%	0% Externa	C0001/C0002
Audi A6 C6	4F0 920 933Q	95%	100%	C0001
<b>BMW</b> 				
S3 E46 1999-2001	6211 6 901 923	85%	0%	C0001
<b>Citroën</b> 				
C4 2005-	P96572391	100%	0%	C0002
C5 II 2005-	965560878000%	100%	0	C0002
<b>Chevrolet</b> 				
Aveo 2006-2007		100%	No lleva	C0001
<b>Dacia</b> 				
Dokker, Sandero, Duster 2013-	248101921R	100%	100%	C0001
<b>Fiat</b> 				
Punto mk2	51744552	100%	100%	C0002
Scudo 99-2005	1488561080	100%	no lleva	C0001
Stilo 2001-2005	46759970	100%	100%	C0002
Stilo 2001-2005	46754571	100%	100%	C0002
<b>Ford</b> 				

Fiesta 2002-2005	2S6F-10849-NE	100%	100%	C0001
Fiesta 2005-2010	6S6T-10849-GE	98%	100%	C0001
Focus mk1 98-2004	1M5F-10849 pB	100%	100%	C0001
Focus mk2 2005-2009	4M5T-10849 6N	98%	100%	C0001
Focus mk2 2005-2009	8V4T10849GE	98%	100%	C0001
Mondeo Mk4	6M2T-10849-CN	98%	100%	C0001
				
<b>Hyundai</b>				
<b>Coupe/Tiburón</b>	2003-45900H	100%	no lleva	C0001
				
<b>Kia</b>				
Cerato 2004-	94003-2F340	100%	No lleva	C0001
				
<b>Mazda</b>				
Mazda 3	4T BN9JA	100%	100%	C0001
Mazda 3 2003-	8F BS3TA	100%	100%	C0001
				
<b>Mercedes</b>				
Clase C W203	A2035404947	100%	*****	C0001 / C0002
Clase S w220	A2205408211	95%	100%	C0001
SLK R171 W171	A1715401147	100%	100%	C0001 / C0002
Sprinter -2005	A0014464521	100%	100%	C0001
				
<b>Nissan</b>				
Micra K12E 1ª	AX8640540	100%	No lleva	C0001
X-Trail 2007-	2482JG62A	100%	100%	C0001
				
<b>Peugeot</b>				
Peugeot 207	9662903880	100%	0%	C0002
Peugeot 307	9661323180	100%	0%	C0002

peugeot 308	9665107480	100%	0%	C0002
Peugeot 407	9658138080	100%	0%	C0002
Expert I	1488561080	100%	No leva	C0001
<b>Renault</b> 				
Clio III 2005-2010	8200582705	100%	100%	C0001
Clio III 2005-2010	820082099	100%	100%	C0001
Kangoo I D	58200133491	100%	No tiene	C0001
Laguna III 2008-2016	248100006R	100%	100%	C0001
Megane I -2002	8200071820	100%	No tiene	C0001
Megane II -2006	2RPF-14B115-AQ	100%	100%	C0001
Megane II 2006-	8200408785	100%	100%	C0001
Megane III 2008-2016	248 100 342R	100%	100%	C0001
Scenic I -2003	8200071811	100%	No tiene	C0001
Scenic II 2003-	8200451506A	100%	100%	C0001
<b>Seat</b> 				
Ibiza (6K2) 99-2004	VDO 11000892402	100%	Externa 0%	C0001
Ibiza (6L1) 2001-2009	VDO 110080104	100%	100%	C0001
Ibiza (6J) 2008-	6J0 920 801A	100%	100%	C0001
Leon 2006-	1P0 920 804C	100%	100%	C0001+Adap.
Leon 2006-	1P0 920 823F	100%	100%	C0001+Adap.
Leon 2006-	1P0 920 847B	100%	100%	C0001+Adap.
<b>Skoda</b> 				
Octavia I	1U1919034G	100%	Externa	C0001
Octavia II	1Z0 920 810E	95%	100%	C0001+Adap.
<b>Toyota</b> 				
Corolla D4D	83800-02760	100%	No lleva	C0001
Corolla D4D	83800-02C60	100%	No lleva	C0001
<b>Volkswagen</b> 				
Caddy -2010	Vdo 110.080.343	100%	100%	C0001
Golf IV / Bora	1J0919880D	100%	Externa 0%	C0001



Golf V	1K0920851B	100%	100%	C0001
Golf VI 2010-2013	5k0 920 862A	100%	100%	C0001
Passat (3B)	1J0919880D	100%	Externa 0%	C0001
Passat (3C)	3C0 920 870Q	100%	100%	C0001
Touran -2006	Vdo 110.080.218	100%		C0001